

**ATTENZIONE - ATTENTION - ACHTUNG**

- Per lo smontaggio degli utensili utilizzare sempre la chiave di contrasto come indicato nel manuale d'uso.
- For disassembly of the tools use always the contrast key as mentioned in the user instructions.
- Fuer das Abmontieren der Werkzeuge immer den Gegenschlüssel benutzen wie in der Bedienungsanleitung erwaeht.


- Chiave inclusa
- Key included
- Schluessel inbegriffen

Cod. MT	Mandrino Spindel Spindel	I	RPM	Coppia Max Max Torque Max Drehmoment	Reversibile lato mandrino/contromandrino Reversible sub/main spindle side Umkehrbare Spindel-seite/ Gegenspindel-seite	Lubr.interna Coolant through Innenkuehlung	Lubr.esterna Ext. coolant Aussenkuehlung	A	CHIAVI NON INCLUSE Keys not included Schluessel nicht einbegriffen		
GDW 0210225	ER25	1:1	6000	40Nm	X	-	X	137.96	CHUB36	CHSTER25	-
GDW 0211225	ER25	1:1	6000	40Nm	X	P=70bar	X	162.66	CHUB36	CHSTER25	-
GDW 0210325	ERA25	1:1	6000	40Nm	X	-	X	126.5	CHUB38	CHUB27	CHTAER25ZC •
GDW 0211325	ERA25	1:1	6000	40Nm	X	P=70bar	X	156.03	CHUB38	CHUB27	-

**GOODWAY**  
 MOD: GS2000/2600/2800/3000/3300/3600/4000 12ST.

MODULO MOTORIZZATO ASSIALE 2 USCITE IN Y  
 Axial Single side twin head driven tool in Y  
 Axial angetriebenes Werkzeug 2 Ausgaenge in Y

Subject to change without notice.



**M.T. srl**  
 Via Casino Albini 480  
 Tel. 0541/956034-957884  
 Fax 0541/956341  
 47842 S. GIOVANNI IN M. (RN)  
 e-mail: mtma@mtmarchetti.com  
 http://www.mtmarchetti.com



**GDW 260-1-10**